

Work Order ID 73301

Wednesday, August 31, 2011 10:46:07 AM



Page 1

Item ID: D3544-041

Accept



Setup Start



Revision ID:

Item Name: Clamp

Stop



Start Date: 9/1/2011 Start Qty: 20.00



Cust Item ID:

Required Date: 9/15/2011 Req'd Qty: 20.00



Customer:

Reference:

Approvals: Process Plan: *MF* Date: *11-09-06*

Tooling:

Date:

Run Start



QC: Date:

SPC (Y/N):

Date:

Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
D3544	Rev A

100	Small Fab	0.00
Small Fab	Memo	0.00
Small Fab	Assemble as per Dwg D3544	

SP 11/09/06 *(20)*

110	QC5- Inspect part completeness to step on W/O	0.00
QC	Memo	0.00
Quality Control		

Substructure

counts
(x20)

120	Identify as per dwg & Stock Location: <i>407</i>	0.00
Packaging	Memo	0.00
Packaging		

SP

(20) SP 11-09-06

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 73301

Wednesday, August 31, 2011 10:46:07 AM



Page 2

Item ID: D3544-041

Accept



Setup Start



Revision ID:

Stop



Item Name: Clamp

Start Date: 9/1/2011 Start Qty: 20.00



Cust Item ID:

Required Date: 9/15/2011 Req'd Qty: 20.00



Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start



QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop

Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

130

QC21- Final Inspection - Work Order Release

0.00



QC

Memo

0.00

Quality Control

11/9/11

MF

11-09-06

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Wednesday, August 31, 2011 10:46:04 AM

Page 1

Work Order ID: 73301

Parent Item: D3544-041

Parent Item Name: Clamp



Start Date: 9/1/2011

Required Date: 9/15/2011

Start Qty: 20.00

Required Qty: 20.00

Comments: IPP Rev:A New Issue 06-08-29 JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2182 Heat Shrink		Manufactured	No			100	f	543.9763	0.585	12.31579		9/11/09/06	
				<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>					
				ST402A		543.97632							
				21864		193.97632							
				26009		256							
				3999		94							
D2947 Clamp		Manufactured	No			100	Each	83.0000	1	20		9/14/09/06	
				<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>					
				ST457		83							
				63320		3							
				72134		80							

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____


Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



DESIGN CB	DRAWN BY CB	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED CP	APPROVED [Signature]	DRAWING NO. D3544	REV. A SHEET 1 OF 1
DATE 06.08.11	TITLE CLAMP		SCALE 1:1
REV A	DATE 06.08.11	DESCRIPTION NEW ISSUE	



D3544-041 CLAMP

RELEASED

06.08.23 [Signature]

COPYRIGHT © 2006 BY DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries